


- 1、connect camera to PC USB interface
- 2、double click burn tool "USB_XU_BurnerAP小.exe"



- 3、Click browse in the open window



- 4、Click Browse in the open window and find the burn file FW:566-RF23-XUJIN_ZYKD2005110301(1).src in the popup window, then click open.



- 5、in the popup window click "start burn"



- 6、Window show burn successfully then ok, after that take off camera and re-plug camera on PC

